

ATTACHMENT B

ATTACHMENT B

Page 3, sixth full paragraph:

A2
Tongue 14 is correspondingly provided in its root portion, i.e. where it joins with left board 10, with a portion 40 of greater thickness which runs into the non-designated front, or outer, portion of tongue 14 via a tapered surface 42. The two tapered surfaces 38 and 42 are essentially contrived with the same angle of inclination of e.g. 45° in relation to the plane of the board. A slight gap is also preserved between these tapered surfaces when the two boards come into contact with each other in the top assembled position 22.

Page 4, second full paragraph:

X2
The front end of bottom groove cheek 34 is also provided with a relatively steep, upwardly inclined tapered surface 44, which is angled upwards at e.g. 60° .

FOUDED 2004-05-10